

Technical Service Bulletin

Bulletin No.	R_01_2025
Date	February 2025

Awning legs

Dear Customer,

in the event of resistance of the sliding part of the legs, we recommend the following action:

